GIPRO X-TYPE GEAR INDICATOR
Supplementary Manual

**KTM 1190 RC8 2008-2010 (GPXT + GPX-KT1)**

Remove the windshield and the left fairing cover at the headlight.

Remove the mirror console and the dashboard unit.

Plug the GPX connectors in-line with the speed sensor connectors.

(White, 3-pole triangular connector below dashboard unit.)

Connect the GPX Black/Green wire to the Black/Brown wire of the dashboard connector.

(Top row, 3rd wire from left to right at the back of the plug.)

GIPRO X-TYPE GEAR INDICATOR
Supplementary Manual

Typical position for the gear indicator.

Secure the unit properly.