

GIPRO X-TYPE GEAR INDICATOR Supplementary Manual



Honda CBR600F4i 2001-2006 (GPXT + GPX-H01)

Remove the seat.

Lift up or remove the fuel tank.




Plug the GPX connectors in-line with the speed sensor connectors.

(Black, 3-pole connectors at the front of rear shock absorber, near the water reservoir)



Connect the GPX Black/Green wire to the Yellow/Green wire of the ECM/ECU.

(Black connector, under the tail fairing next to the left frame)



GIPRO X-TYPE GEAR INDICATOR

Supplementary Manual



Honda CBR600F4i 2001-2006 (GPXT + GPX-H01)

Typical position for the gear indicator.

Secure the unit properly.

